


OCEAN NETWORKS CANADA

ENDEAVOUR RC NORTH OVERVIEW MAY 2022



Cable used for RCM NW (25908)
Connector parked
390m @ 290°

SPS (16001)
24m @ 353°
[calculated]

To RCM-NW (43860)
400m @ 289°
[calculated]

RCM-NE (43840)
37m @ 311°
[calculated]

BPR (74480)
15m @ 5°
[calculated]

New RCM NE mooring LZ
36m @ 302°

Old mooring weight
29m @ 297°

Beacon (74984)
mounted on JB-17

Media converter

JB-17 (24057)

Old gratings from JB-17 (2019)
18m @ 93°
[calculated]

Connector with growth on pins. No parking position.
Screenshots in NEPDATA-20437

Cable lay unclear. Unable to confirm during last dive

Termination can (media converter)
rocks under platform leg & term.can

To Endeavour Node (10101)
4,178 m
[calculated]

unknown cable along ExtID: 397
maybe steel wire for strength

This is the area where oily 707 snagged and broke off.
See NEPDATA-18159 for details

RCM-N IP-end mudmat
35 m @ 260°
[calculated]

BBS West mudmat
46 m @ 233°
[calculated]

To BBS West (11057,23068,23927)

ROCLS gratings

ROCLS LZ

Abandoned oily (broke off during recovery)

Tall rock pillar
49m @ 164°

'Great Wall' - very steep with sharp edges

Hi Lo

Lo Hi

Lo Hi

Lo Hi

Hi Lo

Hi Lo

Rocks

Rocks

Lo Hi

Lo Hi

Lo Hi

moderate drop-off