

Comments:

- Site needs to be re-layed out. This diagram is stitched out of multiple dives, each one showing only small part of this site. Please fly over cables with ROV and JB-15.
- If time allows, more flying around mudmat required.
- Media Converter and Mudmat (NEPDATA-23654)
- Port J7 on JB-15 is faulty - very likely compromised
- It looks like there are two media converters on cable 560, but very likely the further one is rather on the cable that goes to Endeavour Node Mudmat
- Position confirmation for the mudmat



OCEAN NETWORKS CANADA

**ENDEAVOUR
MOTHR
OVERVIEW
JULY 2023**

